

# Front Panel Errata

## Rev 1

- Mode/load switches footprints need soldermask pulled back from pads
  - The pads are covered by soldermask. This is bad

---

Revision #1

Created 6 April 2022 06:40:54

Updated 29 May 2022 04:29:55