

# Rear IO Errata

## Rev 1

- Copper rings around USB connector pads should be larger
- Retention holes for Ethernet jack should be slightly smaller (to accommodate push-in expansion action for mechanical stability)

---

Revision #1

Created 6 April 2022 22:42:43

Updated 29 May 2022 04:29:55